
Question

[Yakov Berger](#) · Jul 21, 2020

Problem With Message/Segment Terminators

Hi,

A device is sending me HL7 messages (ORM^O01)

the framing is set to "None"

and i get the following error:

3 Segments

Build Map Status = 'ERROR <EnsEDI>ErrMapRequired: Missing required PID element at segment 2 (PID)'

'ERROR <EnsEDI>ErrMapRequired: Missing required OBR element at segment 2 (PID)'

'ERROR <EnsEDI>ErrMapSegUnrecog: Unrecognized Segment 2:'PID' found after segment 1 (MSH)'

i seems that there framing chars in at the beginning and end of each segment

(in Hex)

0b (MSH DATA HERE) 1c 0d 0b (PID DATA HERE) 1c 0d 0b (OBR DATA HERE) 1c 0d

i have tried all the Framing options of no help.

how can i fix this ? (i'm a newbie so....)

Thanks

[#InterSystems IRIS for Health](#)

Source URL: <https://community.intersystems.com/post/problem-messagesegment-terminators>